CO₂ Room Sensor, BAPI-Stat "Quantum Prime"

Air Quality Sensors



Features & Options

- New BAPI-Stat "Quantum Prime" Enclosure Style
- Automatic Barometric Pressure Compensation for Accurate Readings Regardless of Weather or Altitude
- Optional Temperature, Setpoint, Override and Humidity
- Models for Periodically Unoccupied or Continuously Occupied Areas

The BAPI CO₂ Sensor is an accurate and reliable way of incorporating demand controlled ventilation into a building's HVAC strategy. It measures the CO₂ in a range of 0 to 2,000 ppm with a field selectable output of 0 to 5 or 0 to 10 VDC.

The Single Channel unit has been optimized for periodically unoccupied areas and features automatic background calibration over a long time period to reduce drift. The Dual Channel "24/7" unit has been optimized for continuously occupied areas and features a three-point calibration process for enhanced stability, accuracy and reliability.

Barometric pressure changes from altitude or weather patterns can affect CO₂ sensors, even putting them outside of their specified accuracy. The BAPI unit has a built-in Barometric pressure sensor that continuously compensates the output for accurate readings despite the weather or altitude of the installation.

The BAPI-Stat "Quantum Prime" unit can be ordered as CO2 alone, or as a combination temperature and humidity sensor. The CO₂ level is indicated as "Good, Fair or Poor" by three discrete green, yellow and red LED's on the front of the unit. The red LED will begin to flash when the unit exceeds 2,000ppm, indicating that fresh air needs to be brought in.







Specifications

Power for 0 to 5 VDC Outputs:

9 to 35 VDC @ 240 mA (9 to 24 VDC recomm.)

Power for 0 to 10 VDC Outputs:

15 to 35 VDC @ 240 mA (15 to 24 VDC recomm.)

CO₂ Sensor:

Single Channel or Dual Channel Non-Dispersive Infrared (NDIR)

Humidity Sensor: Capacitive Polymer ±2% RH Accuracy

Temperature Sensor: Thermistor or RTD

Operating Environment:

32 to 122°F (0 to 50°C) • 0 to 95%RH non-condensing

Material: ABS Plastic, Material Rated UL94V-O

CO₂ Detection Range: 0 to 2,000 ppm

Start-Up Time: <2 Minutes

Response Time:

<2 Minutes for 90% step change typical (after start-up)

CO₂ Accuracy (Single Channel Units):

400 to 1,250 ppm: ±30ppm or 3% of reading,

whichever is greater

1,250 to 2,000 ppm: ±5% of reading + 30ppm

CO₂ Accuracy (Dual Channel "24/7" Units):

75ppm or 10% of reading (whichever is greater)

CO₂ Drift Stability (Dual Channel "24/7" Units):

<5% of full scale over life of product.


Mounting: 2"x4" J-Box or drywall - screws provided

LED CO₂ Level Indicator:

Good, Green < 1,000 PPM

Fair, Yellow = 1,000 to 1,500 PPM

Poor, Red > 1,500 PPM Certifications: RoHS







CO₂ Room Sensor, BAPI-Stat "Quantum Prime"

Air Quality Sensors

Use the Option Selection Guide below to create your custom part number. Replace the number and parenthesis with the designator for each selection. Skip the designator and dashes for optional selections that are not required in your configuration.

BAPI-Stat "Quantum Prime" CO2 Sensor Option Selection Guide:

BA/AQP(#1)-(#2)-(#3)-(#4)-(#5)-(#6)(#7)-(#8)-(#9)

#1: Display Style (required)

- FUnit with Display and °F indication C......Unit with Display and °C indication
- XUnit without Display

#2: CO2 Output (required)

- ASingle Channel, 0 to 5V Output BSingle Channel, 0 to 10V Output
- C......Dual Channel, 0 to 5V Output
- D......Dual Channel, 0 to 10V Output

#3: Temperature Sensor (required)

- A1K Platinum RTD (385 curve)
- B10K-2 Thermistor
- C......10K-3 Thermistor
- D......10K-3[11K] Thermistor
- E20K Thermistor
- F1.8K Thermistor
- G......1K Ω Nickel RTD
- H......3K Thermistor
- X No Temperature Sensor

#4: Humidity Output (required)

- A±2% Accuracy, Output of 0 to 5V B±2% Accuracy, Output of 0 to 10V
- XNo Humidity Output

#5: Setpoint Adjustment (required)

- 1......Slider Setpoint Adjustment
- XNo Setpoint Adjustment

Additional options are available for these units but not shown in this Selection Guide. Contact your BAPI representative for the complete list of options.

#6: Setpoint Display Range (required)

- A-3 to +3
- B-5 to +5
- C......50 to 90 °F or 10 to 32 °C
- D55 to 85 °F or 13 to 30 °C
- E......60 to 80 °F or 15 to 27 °C F65 to 80 °F or 18 to 27 °C
- XNo Setpoint Adjustment

#7: Setpoint Output Range (required)

- 00.....0 to 5 V
- 10.....0 to 10 V
- 40.....0 to 1 k
- 60.....0 to $10~k\Omega$
- 80.....0 to $20 k\Omega$
- 81.....4.75 k to $24.75 \text{ k}\Omega$
- 82.....6.19 k to 26.19 k Ω
- 84.....10 k to 30 kΩ
- X No Setpoint Adjustment

#8: Occupant Override (required)

- J......Override as a Separate Output
- N......Override in Parallel (//) with Sensor
- P......Override in Parallel (//) with Setpoint
- X.....No Override

#9: Optional Selections* (optional)

- ADifferential Ground
- B......Comm Jack C35
- FTest and Balance Switch

Example Number:

BA/AQP(F)-(A)-(B)-(A)-(1)-(F)(80)-(N)

Actual Number (with brackets removed): BA/AQPF-A-B-A-1-F80-N

Description: BAPI-Stat "Quantum Prime" CO2 Sensor, °F Display, 0 to 5V Single Channel CO2 Output, 10K-2 Thermistor Temperature Sensor, 0 to 5V Humidity Output, Sider Setpoint Adjustment, 65 to 80 Temp Setpoint Display Range, 0 to 20K Temp Setpoint Output Range, Override in Parallel with the temp sensor, No Additional Options

Your Number: BA/





^{*}When more than one is selected, put in alphabetical order. Additional options and descriptions can be found on pg. 14